

# Diagramme des accessoires de nos Balances manométriques

-----  
(Accessories's diagram for our  
Dead weight testers)



Ajouter de la fonctionnalité  
(Add functionality)



OP0004 motorisation/visualisation  
Leds  
(Motorization/visualization LCD)




OP0301 automate de calcul  
(calculator)

Raccords de connexion (Adaptors)



OP0037 mallette 17 raccords  
(Suitcase with 17 adaptors)



Balances manométriques Gamme BH2 ou BA2  
(dead weight testers Range BH2 or BA2)

Accessoires divers  
(Optional accessories)



OP0023 séparateur liquide/liquide  
(separator liquid/liquid only)



OP0194 réglage fin (adjust value)



OP236-908 sortie au dos  
(horizontal adapter)

Rampe de contrôle manomètres  
(Ramp for pressure gauges)



Rampe (Ramp) OP0305 ou OP0304



Bloc OP0303